

Tech Talk #15

SHEETFED FOUNTAIN SOLUTION TROUBLESHOOTING

It's the middle of third shift on Saturday night, and the press is not delivering acceptable print quality. You've replaced the ink, changed blankets and plates, and reset the rollers – nothing seems to make a difference. One important variable is left to be checked – the fountain solution – but you don't know where to start or what to look for!

At Printers' Service, we maintain an extensive network of Technical Service Representatives who form an important part of our "value added" package. In this Tech Talk we will share with you some of their ideas on troubleshooting pressroom printing problems that may be fountain solution-related.

On the following pages you will find a series of troubleshooting guides that are divided into sections: Problem, Possible Cause and Suggested Remedy. The guides concentrate on possible fountain solution-related causes for some of the most common problems seen on sheetfed presses.

We urge you to use these guides as a starting point for fountain solution troubleshooting. Of course, not all potential problems are listed, and the cause and/or remedy may turn out to be something other than shown.

Some of the remedies may seem contradictory. The offset printing process involves a specific balance between the composition of the fountain solution, and the amount applied during printing. Excessive dot gain, for instance, can be due either to low fountain solution dosage (leads to high water metering speeds which force too much water into the ink, thinning it out) or to dosage that is too high (excessive chemistry causes the ink to emulsify and break down).

FOUNTAIN SOLUTION/DAMPENING SYSTEM TROUBLESHOOTING GUIDE

Problem	Possible Cause	Suggested Remedy
Slow Initial Roll-ups	Dosage too low	Increase dosage
	 Water speeds too low 	Raise water metering
	 Water metering nip too tight 	speeds
	Excess Ink	Reduce pressures slightly
		 Reduce ink sweep and/or
	 Excess finishing gum 	lighten setting to plate
		Wash plate – warm water
Slow/Poor Restarts	 Dosage too low 	Increase dosage
	 Sensitive plates 	Clean with plate cleaner
	 Too little plate protectants 	Change fountain solution
	 Excessive downtime 	 "Gum in" plates
	 Water form lifting early 	 Revise shutdown
	 Plate dries out too much 	procedure
		Change fountain solution
High Water Metering	 Dosage too low 	 Increase dosage
Speeds	 Insufficient wetting 	Revise dosage to increase
	• Dampening system nips too tight	 Lighten up settings
	 Metering/water from durometers 	 Replace with proper
	too high	durometer
Scumming/Dry-Ups at	 Dosage too low 	 Increase dosage
Outer Edges of Form	 Insufficient wetting 	Revise dosage to increase
	Too much pressure-dampening	 Lighten up settings
	system roll ends	
	Insufficient skew	Increase if possible
Roller Stripping	 Fountain solution less than pH 3.5 	Change fountain solution
	 High water speeds causing 	Revise dosage to reduce
	waterlogged ink	water speeds
	 Ink Water Pick-up Units too low 	 Reformulate ink
	 Glazed ink rollers 	Remove glaze
	 Dosage too high 	Reduce dosage
Emulsified Roller Train	 Fountain solution less than pH 3.5 	Change fountain solution
	High water speeds	Revise dosage to reduce water speeds
	 Ink/fount incompatibility 	Change fountain solution
	 Dosage too high 	 Reduce dosage
	 Ink water pick up to low 	 Reformulate ink

FOUNTAIN SOLUTION/DAMPENING SYSTEM TROUBLESHOOTING GUIDE

Problem		Possible Cause		Suggested Remedy
Ink Piling	•	Fountain Solution less than	•	Change fountain/solution
_		pH 3.5		C C
	٠	Ink/fount imcompatibility	٠	Change fountain solution
	•	Blanket under-packed	٠	Increase packing .001" to
				.002"
	•	Not enough release agent in the ink	•	Reformulate ink
	•	Ink too tacky/too stiff/dries too fast on roller/plates	•	Reformulate ink
	•	Poor blanket release	•	Quicker release type blanket
Tinting/Toning	•	Fountain solution pH less than pH 3.5	•	Change fountain solution type
	•	Dosage too low	•	Increase dosage
	•	Ink breaking down	•	Revise dosage to decrease
		ç		wetting/reformulate ink
	٠	Sensitive plates	٠	See Sens. Plate Remedies
	•	Fountain solution higher than	٠	Replace with fresh solution
		pH 5.5		
Ink Stays Wet Too	٠	Fountain solution less than	٠	Change fountain solution
Long		рН 3.5		
	•	Ink film too thick/ink too weak	٠	Reduce settings/reformulate
	•	Too much water in ink/ink is		ink
		waterlogged	٠	Revise dosage to reduce
	•	Not enough/wrong drier		water settings
	•	Paper too acidic	٠	Consult ink vender
			٠	Change paper
Plate Staining/Picture	•	Improper ink/water balance	•	Revise dosage to change
Framing		Teeseld		wetting /change solution
Foam In Reservoir	•	Too cold	•	Raise to about 15° C ± 8%
	•	Solution contaminated	•	Dump and replace with fresh
Beer Ink Bub/Souff	•	Mechanical reasons	•	Many - see our TechTalk
Poor Ink Rub/Scuff	•	Ink film too thick Not enough/wrong wax	•	Reduce settings/reformulate ink
	•	and/or slip agents		Consult ink vendor
Fountain solution less	•	Fountain solution concentrate	•	Consult link verticion Change fountain solution type
than pH 3.5		is too acidic for the water used		Change fountain solution type
	•	Excessive use of pH-lowering additives	•	Reduce/eliminate use
Scumming – one side of press only	•	Improper roller settings	•	Reset rollers
Rapid increase in pH and/or conductivity	•	Inadequate buffer capacity	•	Change solution to one with more buffer capacity
	•	Dosage too low	•	Increase dosage (provides more buffer capacity)
	•	Inadequate filtration	•	Improve filtration system

FOUNTAIN SOLUTION/DAMPENING SYSTEM TROUBLESHOOTING GUIDE

	 Excess materials leaching out of paper and ink 	Consult vendors		
Feedback in dampening system	 Improper ink/water balance – water too low and/or high for the amount of ink Sensitive chrome roller 	 Change water metering settings Desensitize chrome roller 		
Color Variation (surging)	 Ink/Fount incompatibility Too much wetting Ink/fount incompatibility 	 Change fountain Solution Revise dosage to reduce Change fountain solution type 		
Paper Piling on non-	Ink improperly formulated	Consult ink vendor		
image areas of blanket	Dosage too lowNot enough anti-pile	 Increase dosage Add separate anti-pile or switch to solution that contains more anti-pile 		
	 Under-packed blanket Water speeds too low Paper with poor water resistance 	 Add .025050mm packing Raise slightly Reduce water speeds or consult paper vendor 		
Excessive Dot Gain	 Improper dosage – too low or too high 	Revise dosage		
	High water speedsBlankets over-packedInk too soft/too low in tack	 Increase dosage/wetting Reduce packing .025050mm Reformulate ink 		
Rapid increase in conductivity, pH stays relatively constant	 Excessive use of additives such as fountain drier Poor stock 	Reduce/eliminate useConsult paper vendor		
Mottled/Snow flaked Dots	 More water than ink can emulsify Water speeds too high 	 Increase ink WPU Revise dosage to reduce 		
	 Poor quality emulsion 	 water speeds Consult ink and fountain solution vendors 		

10/05

As always, your local PRINTERS' SERVICE office is happy to answer your questions:

Atlanta (800) 241-6049 • (404) 602-4140 • (404) 602-4139 Fax Miami (800) 432-5068 • (954) 385-1975 • (954) 385- 8875 Fax Boston (781) 749-4590 • (781) 740-2866 Fax New York/Newark (973) 589-7800 • (212) 962-6565 • (973) 589-3225 Fax Chicago (800) 654-1357 • (630) 543-4600 • (630) 543-0856 Fax Dallas (800) 338-2241 • (817) 477-4770 • (817) 473-4515 Fax Los Angeles (800) 825-4846 • (909) 923-1879 • (909) 923-4079 Fax Toronto (888) 460-4406 • (905) 953-9393 • (905) 953-1331 Fax Philadelphia (800) 222-0146 • (856) 662-3373 • (215) 462-3636 • (856) 486-4552 Fax

U.K. +44 (0) 1423 810 320 • +44 (0) 1423 810 319 Fax **Belgium** +32 56 40 41 82 • +32 40 41 83 Fax

SERVICE AND TECHNOLOGY FOR THE GRAPHIC ARTS®

PRINTERS' SERVICE 26 Blanchard Street • Newark, NJ 07105 • www.prisco.com • (973) 589-7800 • (973) 589-3225 Fax